Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-394962
Estimate date:	15 Mar 2025
Customer:	Laurie Johnson
Phone:	713-555-4473
Insurance claim:	C-1062
Vehicle:	2011 Ford F-150
VIN:	F3ZRHSAG7GSMB3435
License plate:	LDV 560

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$514.74
Left quarter panel	1	$483.51
Headlamp assembly	1	$296.46
Body labor	17.5 hrs	$1,189.83
Paint and materials		$664.45
TOTAL		$3,148.99

Appraiser remarks

Inspection of the driver's side shows crushed rear door panel, a bent B-pillar, and scraping along the rocker that line up with a side impact at an intersection. The damage pattern is consistent with the account given, and no older damage is known on this vehicle. The repair plan calls for replacing the rear door, straightening the pillar, and refinishing the affected panels. The labor hours submitted fit the work needed, and the parts and paint charges show no duplicate entries. Repairs can proceed as written.