Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-852531
Estimate date:	15 Feb 2024
Customer:	Christy Fowler
Phone:	832-555-1165
Insurance claim:	C-1065
Vehicle:	2019 Toyota Camry
VIN:	
License plate:	290CJ

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$679.68
Left front fender	1	$599.49
Front bumper cover	1	$384.34
Body labor	17.9 hrs	$1,218.49
Paint and materials		$514.85
TOTAL		$3,396.85

Appraiser remarks

Inspection of the rear quarter panel and passenger-side door shows scraping, a crease along the lower door skin, and a cracked rear bumper cover end, all consistent with a sideswipe wihle changing lanes as described. The damage pattern lines up with the reported impact, and nothing observed suggests older or unrelated harm. The repair plan calls for replacing the bumper cover, blending and refinishing the quarter panel, and straightening and refinishing the door. The labor hours requested fit the extent of the work, and the supporting invoices show no repeated charges. No prior damage to this vehicle is known to us.