Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-164894
Estimate date:	12-8-23
Customer:	Caleb Peterson
Phone:	346-555-6365
Insurance claim:	C-1066
Vehicle:	2012 Hyundai Elantra
VIN:	0HBCM0MR1KR5V0085
License plate:	LBK Y20

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,287.91
Headlamp assembly	1	$1,342.47
Right front door shell	1	$954.01
Body labor	30.4 hrs	$2,065.53
Paint and materials		$1,379.09
TOTAL		$7,029.01

Appraiser remarks

Front bumper cover cracked across the left side with the lower valance torn free, and the left headlamp assembly broken at its mounting tabs. The damage pattern lines up with the reported strike while turning left, with the impact landing at the fornt corner. Repair plan calls for replacing the bumepr cover, headlamp, and left fender bracket, followed by refinishing and a sensor recalibration. Labor hours are in line with the extent of the damage shown. The shop's billing reflects one set of charges with no repeated line items. Nothing on the vehicle suggests earlier damage to these areas.