Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-992513
Estimate date:	01/25/2024
Customer:	Jose Shields
Phone:	832-555-8155
Insurance claim:	C-1069
Vehicle:	2010 Ford F-150
VIN:	UGDDC1KP93SSS9692
License plate:	531R

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$644.47
Front bumper cover	1	$582.94
Right front door shell	1	$346.15
Body labor	20.0 hrs	$959.00
Paint and materials		$508.69
TOTAL		$3,041.25

Appraiser remarks

The front bumper cover is cracked across the center and the radiator support brackets are bent, which fits the low-speed frontal impact described. The hood latch and both headlamp assemblies show secondary damage that follows from the same force. Repair is planned as replacement of the bumper cover, the headlamps and the latch, with straightening of the support brackets and a new radiator support. The estimated labor hours run a little above what this damage usually needs, so the hours should be reviewed line by line before approval. No earlier damage to this vehicle is on record, and the parts and charges submitted show no rpeeated billing.