Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-906952
Estimate date:	5-24-23
Customer:	Michael Castaneda
Phone:	832-555-4601
Insurance claim:	C-1070
Vehicle:	2011 Jeep Cherokee
VIN:	BYSWUYXY4U5DK5935
License plate:	ITC-953

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,287.35
Rear bumper reinforcement	1	$1,323.72
Rear bumper cover	1	$840.56
Body labor	41.4 hrs	$2,811.82
Paint and materials		$1,248.31
TOTAL		$7,511.76

Appraiser remarks

The rear bumper cover is cracked and the trunk lid edge is bent, with the tail light assembly broken loose on the driver side. The damage pattern lines up well with the rear-end impact that was reported, and nothing in the photos points to older harm on the vehicle. The plan is to replace the bumper cover, straighten the lid flange, and install a new tail light assembly, then refinish the affected panels. The labor hours requested are consistent with this scope of work, and the parts and charges listed show no repeated entries.