Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-650807
Estimate date:	November 25, 2024
Customer:	Mary Baker
Phone:	713-555-5184
Insurance claim:	C-1071
Vehicle:	2020 Hyundai Elantra
VIN:	X7PPVCAY8MK7W7011
License plate:	GUZ-2609

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$842.33
Front bumper cover	1	$568.59
Left quarter panel	1	$484.03
Body labor	23.2 hrs	$1,577.98
Paint and materials		$853.34
TOTAL		$4,326.27

Appraiser remarks

The rear bumper cover is cracked across its center with the left tail lamp housing broken, and the damage sits lragely where a low-speed reversing impact would put it. Paint transfer and scuffing along the left quarter panel line up with the reported contact. A few fine scratches on the right rear door look older than this incident and have been noted separately. The repair plan calls for replacing the bumper cover and tail lamp, refinishing the quarter panel, and a light blend on the adjacent panel. The labor hours requested are consistent with the work described, and the line items show no duplicated charges. Recommend approval as submitted.