White Auto Body

0084 Dana Terrace
League City, TX
Phone 713-555-0947

Repair Estimate

Estimate number:	EST-766913
Estimate date:	02/14/2023
Customer:	Adam Smith
Phone:	713-555-2097
Insurance claim:	C-1073
Vehicle:	2020 Chevrolet Malibu
VIN:	9YCXG8M05462B0941
License plate:	NBP-819

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,399.08
Hood panel	1	$1,867.92
Headlamp assembly	1	$1,035.52
Body labor	62.0 hrs	$2,974.31
Paint and materials		$1,353.90
TOTAL		$8,630.73

Appraiser remarks

Appariser remarks: The right rear quarter panel and rear bumper coevr show scraping and a cracked corner consistent with a sdieswipe during a lane change, and the pattern of contact matches the account given. The repair plan calls for panel straightening, refinishing, and replacement of the bumper cover, with labor hours running somewhat high for this scope, so I have asked the shop to review the time allowances. Shop records show no repeated charges, and I have found no sign of earlier damage to this vehicle in the file.