Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-935651
Estimate date:	02/26/2024
Customer:	Roberta Barnett
Phone:	713-555-7863
Insurance claim:	C-1075
Vehicle:	2010 Hyundai Elantra
VIN:	0U48PAD38SRCE2999
License plate:	35F 654

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,364.16
Left front fender	1	$1,469.23
Hood panel	1	$664.39
Body labor	37.5 hrs	$2,553.13
Paint and materials		$1,482.46
TOTAL		$7,533.37

Appraiser remarks

The vehicle presents with crushed and creased sheet metal along the driver-side door panels and rocker area, with a bent B-pillar and a cracked side window frame. The pattern of deformation runs front to back and matches a side strike at an intersection as described. The proposed plan calls for replacing both front and rear doors, straightening the pillar, and refinishing the affected panels. The labor hours requested fit the extent of this damage, and the parts list shows no duplicated line items. Nothing in the file points to prior damage on this unit, so the estimate is recommended as submitted.