King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-946674
Estimate date:	October 3, 2023
Customer:	Joseph Johnson
Phone:	832-555-9856
Insurance claim:	C-1076
Vehicle:	2014 Nissan Altima
VIN:	83F4NKJV6YVD03857
License plate:	538-KUV

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,633.96
Front bumper cover	1	$1,222.83
Hood panel	1	$1,270.27
Body labor	46.3 hrs	$3,150.84
Paint and materials		$1,356.95
TOTAL		$8,634.85

Appraiser remarks

Front bumper cover cracked across the center with the left headlamp assembly broken and the hood leading edge bent. The radiator support shows deformation that may or may not stem from this collision, so the question of whether all listed damage belongs to this impact remains open and will be checked during teardown. Repair plan calls for replacing the bumper cover, headlamp, and hood, with straightening of the radiator support. The invoices show no repeated charges, and the labor hours fit the extent of the damage. No prior damage to this vehicle is known to me.