Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-202936
Estimate date:	17 Sep 2024
Customer:	Daniel Carr
Phone:	
Insurance claim:	C-1077
Vehicle:	2011 Kia Sorento
VIN:	K800Y0XS8P8CH5314
License plate:	UBB-5455

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$499.42
Right front door shell	1	$282.37
Front bumper cover	1	$313.99
Body labor	10.1 hrs	$685.36
Paint and materials		$441.58
TOTAL		$2,222.72

Appraiser remarks

The rear bumper cover is cracked across the lower center and the left taillgiht assembly is shattered, with scuffing and paint transfer running along the left quarter panel. The damage lines up with the low-speed impact described in the loss report, and the pattern of contact points is consistent with a vehicle backing into or being struck by a stationary object in a parking lot. No prior damage to this vehicle is known from our records or the owner's account. The proposed repair covers replacing the bumper cover, the taillight assembly, and refinishing the left quatrer panel, with labor hours that fit the scope of this work. The invoices submitted so far show each line item billed once, with no duplicate charges. Recommend approval of the estimate as written.