Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

Repair Estimate

Estimate number:	EST-422126
Estimate date:	05/14/2023
Customer:	Michael Carter
Phone:	832-555-0359
Insurance claim:	C-1078
Vehicle:	2014 Kia Sorento
VIN:	SFH91EKZ7SUJX1242
License plate:	XNJ 404

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$850.28
Front bumper cover	1	$1,180.64
Left front fender	1	$794.66
Body labor	27.9 hrs	$1,898.06
Paint and materials		$1,187.77
TOTAL		$5,911.41

Appraiser remarks

The rear bumper cover is cracked across its lower center, with the left tail lamp housing broken and the trunk lid edge scuffed in a way that lines up with the reported strike. The damage pattern is consistent with the imapct described, and nothing in the inspection suggests older wear or a prior repair on this area. The repair plan calls for replacing the bumper cover, the tail lamp assembly and refinishing the trunk lid, with labor hours that match the work needed for this damage. The shop's invoice lines show one charge per part and labor operation, with no duplicate entries. Overall the estimate reflects a single, straightforward collision repair.