Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-898222
Estimate date:	2025-02-26
Customer:	Benjamin Nash
Phone:	
Insurance claim:	C-1081
Vehicle:	2010 Hyundai Elantra
VIN:	W55B66RW2PCEE9323
License plate:	LIQ-4951

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$760.83
Left front fender	1	$509.19
Headlamp assembly	1	$519.92
Body labor	17.1 hrs	$1,161.07
Paint and materials		$726.05
TOTAL		$3,677.06

Appraiser remarks

Front bumper cover cracked across the center with the lower valance torn free, and the hood leading edge bent upward where it met the impact. The radiator support shows a shallow buckle, and the left headlamp assembly is cracked at its mounting tab. Damage pattern is consistent with the reported frontal contact at low speed, and no prior damage to the vehicle is known from the records reviewed. Proposed plan is to replace the bumper cover, valance, hood and headlamp, and to straighten the radiator support before refinishing. Labor hours submitted fit the scope of this damage. Two similar charges posted to this file on the same day are currently under review and will be confirmed before payment is released.