Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-124179
Estimate date:	04/29/2025
Customer:	Jessica Phillips
Phone:	281-555-9264
Insurance claim:	C-1082
Vehicle:	2011 Jeep Cherokee
VIN:	307W1HV49AEDX1259
License plate:	56-UR81

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,888.39
Right tail lamp assembly	1	$1,158.61
Rear body panel	1	$1,068.68
Body labor	66.6 hrs	$3,196.31
Paint and materials		$1,762.95
TOTAL		$9,074.94

Appraiser remarks

The rear bumper cover is cracked across the center with the left taillight assembly broken, and the trunk lid shows a crease consistent with the rpeorted rear impact. The damage pattern lines up well with how the collision was described, and nothing I found suggests earlier damage to this vehicle. The repair plan calls for replacing the bumper cover and taillight, refinishing the trunk lid, and checking the rear sensors. Labor hours on the estimate run slightly high for this scope of work, so I recommend a line-by-line review with the shop. The invoices provided show no repeated charges.