Osborne Auto Body

870 Samantha Crossing
League City, TX
Phone 281-555-7889

Repair Estimate

Estimate number:	EST-100298
Estimate date:	27 Jul 2024
Customer:	Olivia Taylor
Phone:	832-555-6547
Insurance claim:	C-1084
Vehicle:	2015 Kia Sorento
VIN:	CJP8VEA94VWZU2931
License plate:	94ZH750

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,017.59
Left quarter panel	1	$1,250.04
Headlamp assembly	1	$615.78
Body labor	31.4 hrs	$2,134.54
Paint and materials		$848.98
TOTAL		$5,866.93

Appraiser remarks

Vheicle was inspected at the shop following a collision while making a left turn. The front driver-side bumper cover is cracked and the headlamp assembly is broken, with the fender showing crush damage that lines up with the reported point of impact. A few older scratches along the rear quarter panel may predate this loss and have been noted separately. Repair plan calls for replacing the bumper cover and headlamp, straightening the fender, and refinishing the affected panels. The labor hours requested are consistent with the extent of damage seen. Parts and labor charges on the submitted invoices show no repeated entries.