Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-223640
Estimate date:	February 8, 2024
Customer:	Carrie Hatfield
Phone:	713-555-3806
Insurance claim:	C-1086
Vehicle:	2015 Honda Civic
VIN:	J8J16DZP78JAT6993
License plate:	ADF 017

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$930.99
Headlamp assembly	1	$987.97
Left front fender	1	$805.25
Body labor	30.6 hrs	$1,469.61
Paint and materials		$934.00
TOTAL		$5,127.82

Appraiser remarks

The vehicle shows damage to the left front quarter panel, front bumper cover, and headlamp assembly, which fits the reported impact while turning left. The rear-side area shows minor scuffing that matches the same event. Nothing on the car points to older damage, and no earlier repair history has come to light. The shop's invoices list no repeated charges for the same parts or labor. The labor hours look a little high for this scope of work, so I recommend a line-by-line review before approval. Repair plan: replace the bumper cover and headlamp, repair and refinish the quarter panel, and recheck alignment after reassembly.