Jones Auto Body

738 Jennifer Ports Suite 376
Sugar Land, TX
Phone 713-555-1656

Repair Estimate

Estimate number:	EST-797888
Estimate date:	12/17/2024
Customer:	Patrick Singh
Phone:	281-555-9685
Insurance claim:	C-1088
Vehicle:	2018 Jeep Cherokee
VIN:	
License plate:	95ZK194

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,187.38
Headlamp assembly	1	$838.12
Front bumper cover	1	$768.52
Body labor	25.8 hrs	$1,756.28
Paint and materials		$806.28
TOTAL		$5,356.58

Appraiser remarks

Inspection of the frnot end shows a crushed bumper cover, a cracked grille, and a bent radiator support, all of which line up with a low-speed frontal impact as described. The damage pattern is consistent across the bumper bar, headlamp mounts, and hood leading edge, with no sign of older rpeair work or unrelated wear in the affected areas. Labor hours and parts listed on the estimate are reasonable for this scope. Repair plan: replace the bumper cover and grille, straighten the radiator support, install new headlamp brackets, refinish the hood edge, and run a full post-repair scan. Invoices on file contain no duplicate line items.