Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-773571
Estimate date:	17 Jan 2023
Customer:	James Castillo
Phone:	713-555-1851
Insurance claim:	C-1089
Vehicle:	2014 Kia Sorento
VIN:	5UXVCB5J41D929997
License plate:	MUJ 743

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$1,057.33
Rear bumper cover	1	$889.75
Rear bumper reinforcement	1	$750.61
Body labor	23.5 hrs	$1,596.69
Paint and materials		$771.06
TOTAL		$5,065.44

Appraiser remarks

Rear bumper cover cracked across the center with the lower valance torn free, and the trunk lid edge is bent where the impact load was carried into the panel. The damage pattern lines up with the rear-end collision as described, and nothing in the inspection points to older or unrelated harm. The planned repair is to replace the bumper cover and valance, straighten and refinish the trunk lid edge, and recalibrate the rear sensors. The billed parts and paint charges show no repeated entries, and the labor hours estimated are in line with the work that the damage calls for.