White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-500926
Estimate date:	May 27, 2024
Customer:	Nicole Wood
Phone:	713-555-8625
Insurance claim:	C-1090
Vehicle:	2021 Chevrolet Malibu
VIN:	6EWA3HZX78GLM3045
License plate:	734-NQZC

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$819.35
Left front fender	1	$712.03
Front bumper cover	1	$449.00
Right front door shell	1	$819.35
Body labor	61.6 hrs	$1,354.14
Paint and materials		$695.98
TOTAL		$4,849.85

Appraiser remarks

The vehicle shows crush and paint transfer along the driver side rear quarter panel, consistent with the side impact at the intersection, and the damage pattern lines up with the account given. Structural measurements are within tolerance and no prior damage is recorded on this vehicle. The estimate, however, lists repair labor at roughly three times what this extent of damage would normally require, and the shop's own invoice history shows the same service billed twice on one date, which the provider has acknowledged was a repeat charge. Recommend the labor hours be reviewed line by line, the duplicate charge removed, and the panel replacement scope confirmed before approval. Repairs can proceed on the front bumper once the revised figures are returned.