Osborne Auto Body

870 Samantha Crossing
League City, TX
Phone 281-555-7889

Repair Estimate

Estimate number:	EST-402828
Estimate date:	21 May 2025
Customer:	Brett Torres
Phone:	281-555-6268
Insurance claim:	C-1091
Vehicle:	2011 Ford F-150
VIN:	
License plate:	667 WJR

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,624.22
Hood panel	1	$1,198.02
Right front door shell	1	$1,273.67
Body labor	68.5 hrs	$3,287.94
Paint and materials		$1,595.11
TOTAL		$8,978.96

Appraiser remarks

The rear bumper cover is cracked across the lower center, and the left tail lamp housing is broken with the lens split. Scuffing and paint transfer on the rear quarter panel line up with the reported strike, and the damage pattern is consistent with the impact described. No earlier damage to this vehicle is known from the records or inspection. The bills submitted show no repeated charges. Repair labor hours run slightly above what this scope of work normally requires, so I recommend a line-by-line review before approval. Plan: replace the bumper cover, tail lamp assembly, and rear quarter panel refinish, with a recheck of sensor alignment after reinstallation.