Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-630470
Estimate date:	1-4-24
Customer:	Paige Wiggins
Phone:	832-555-0576
Insurance claim:	C-1092
Vehicle:	2016 Honda Civic
VIN:	T7LKH0T63DVL08455
License plate:	EXU 9508

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$732.36
Left tail lamp assembly	1	$621.80
Rear bumper cover	1	$467.42
Body labor	72.5 hrs	$1,595.90
Paint and materials		$727.15
TOTAL		$4,144.63

Appraiser remarks

The vehicle presents with damage to the rear bumper cover, the left tail lamp assembly, and the trunk lid, consistent with a rear impact. Some of the lower panel deformation and the wiring harness conidtion may predate this loss, and the file does not make it fully clear whether every listed area was caused by this event. Our records show no earlier damage to this vehicle. The shop's labor hours run roughly three times what this scope of work should require, so the plan needs a line-by-line review. Recommended approach: replace the bumper cover and tail lamp, repair the trunk lid, and re-verify the labor times before approval. The invoices themselves show no duplicate charges.