Shea Collision Center

75655 Mia Isle Suite 746
Houston, TX
Phone 346-555-1545

Repair Estimate

Estimate number:	EST-587680
Estimate date:	August 14, 2024
Customer:	Brandon May
Phone:	832-555-9001
Insurance claim:	C-1093
Vehicle:	2023 Jeep Cherokee
VIN:	
License plate:	501 5269

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$1,336.27
Left tail lamp assembly	1	$1,262.36
Rear bumper reinforcement	1	$808.94
Body labor	38.9 hrs	$2,642.93
Paint and materials		$1,515.26
TOTAL		$7,565.76

Appraiser remarks

The rear bumper cover is cracked across the center and the tail lamp housing on the driver side is broken, with the trunk lid panel showing a crease and paint transfer along the lower edge. The quarter panel has a dent that matches the impact area. Some scuffs and a few older scratches on the lower panel may predate this collision, and it is not clear whether all of the damage came from this impact. The repair plan calls for replacing the bumper cover and tail lamp, repairing and refinishing the trunk lid, and blending adjacent paint. The labor hours listed fit the damage described. The invoices submitted show no repeated charges.