# Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-349172 |
| **Estimate date:** | 8-1-24 |
| **Customer:** | Eric Morris |
| **Phone:** | 713-555-5720 |
| **Insurance claim:** | C-1094 |
| **Vehicle:** | 2024 Chevrolet Malibu |
| **VIN:** | |
| **License plate:** | UIW-8696 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Left front fender | 1 | $373.78 |
| Left quarter panel | 1 | $233.17 |
| Hood panel | 1 | $254.63 |
| Body labor | 9.5 hrs | $647.89 |
| Paint and materials | | $256.39 |
| TOTAL | | $1,765.86 |

### Appraiser remarks

Vehicle inspected at the shop following a left-turn collision. The damage to the front driver-side quarter panel, bumper bracket, and headlamp assembly lines up with the impact as described by the parties. Repair plan calls for replacing the bumper cover, straightening the fender, and refinishing the affected panels, with labor hours that fit the extent of the damage. Invoices reviewed show no repeated charges for the same work. No prior damage to this vehicle is known from our records or the owner's account.