White Auto Body

0084 Dana Terrace
League City, TX
Phone 713-555-0947

Repair Estimate

Estimate number:	EST-244509
Estimate date:	08/22/2023
Customer:	Todd Lee
Phone:	346-555-9050
Insurance claim:	C-1097
Vehicle:	2018 Chevrolet Malibu
VIN:	FV34H6YK3V6RF4368
License plate:	ONF-1577

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,025.19
Rear body panel	1	$778.33
Trunk lid	1	$751.28
Body labor	25.1 hrs	$1,707.36
Paint and materials		$1,132.98
TOTAL		$5,395.14

Appraiser remarks

The rear bumper cover is cracked across the center with the left tail lamp housing broken, and the trunk lid shows a crease that lines up with the reported impact. Crush and paint transfer on the rear panel are consistent with a rear-end strike, and no earlier damage to the vehicle is known. The repair plan calls for replacing the bumper cover and tail lamp assembly, straightening and refinishing the trunk lid, and rcealibrating the parking sensors. The labor hours requested fit the extent of the damage, and the invoices show no repeated charges for the same operations.