Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-561800
Estimate date:	April 27, 2023
Customer:	Sarah Foster
Phone:	713-555-9497
Insurance claim:	C-1099
Vehicle:	2023 Kia Sorento
VIN:	FDNUG5W018U9G5601
License plate:	TJU 762

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$942.94
Rear bumper cover	1	$1,015.40
Rear body panel	1	$878.19
Body labor	32.5 hrs	$2,206.86
Paint and materials		$1,459.33
TOTAL		$6,502.72

Appraiser remarks

The rear bumper cover is cracked across its center with the mounting brackets broken, and the trunk lid shows a crease with the tail lamp assembly displaced. The pattern of the damage lines up well with a straight rear-end impact of the kind reported, and nothing we found points to older or unrelated harm. The planned repair involves replacing the bumper cover and tail lamp, straightening and refinishing the trunk lid, and checking the rear panel for hidden deformation before final sign-off. The labor time requested is consistent with the work described, and the parts invoices show each item billed once with no duplicate entries.