Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-503127
Estimate date:	08/05/2023
Customer:	Garrett Cook
Phone:	832-555-3251
Insurance claim:	C-1100
Vehicle:	2021 Hyundai Elantra
VIN:	J5HA40JK1HP1D3507
License plate:	80F 9997

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,445.69
Right front door shell	1	$1,223.30
Left quarter panel	1	$746.24
Body labor	30.3 hrs	$2,059.18
Paint and materials		$1,253.65
TOTAL		$6,728.06

Appraiser remarks

The rear bumper cover is cracked across the center with the left taillight assembly broken, and the trunk lid shows a crease near the latch. Damage to the quarter panel looks consistent with the reported low-speed contact in the parking lot. The repair plan calls for replacing the bumper cover and taillight, straightening the trunk lid, and refinishing the affected panels. Labor hours are reasonable for this scope, and the parts listed match the damage shown in the photographs. Nothing in the file suggests earlier damage to this vehicle.