Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-926936
Estimate date:	April 28, 2024
Customer:	Gregory Harper
Phone:	832-555-8728
Insurance claim:	C-1101
Vehicle:	2021 Jeep Cherokee
VIN:	
License plate:	073ZY

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$996.60
Rear bumper cover	1	$906.57
Rear bumper reinforcement	1	$478.14
Body labor	34.8 hrs	$1,670.83
Paint and materials		$758.17
TOTAL		$4,810.31

Appraiser remarks

The rear bumper cover is cracked across the center and the trunk lid shows a creased lower edge, with the tail lamp assebmly broken on the driver side. The pattern of damage lines up well with the reported impact, and no prior damage to the vehicle is known from the records available. The plan is to replace the bumper cover, repair the trunk lid, and install a new tail lamp assembly, followed by refinishing and a wheel alignment check. Two similar charges posted on the same day are currently under review. The labor hours on the estimate run a little high for this scope of work, so the shop has been asked to justify the fgiures before approval.