Jones Auto Body

738 Jennifer Ports Suite 376
Sugar Land, TX
Phone 713-555-1656

Repair Estimate

Estimate number:	EST-409241
Estimate date:	07/03/2024
Customer:	Jeanne Robertson
Phone:	346-555-5357
Insurance claim:	C-1103
Vehicle:	2016 Toyota Camry
VIN:	AB9L6GMN0W9EY7953
License plate:	4-14264B

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,732.08
Left front fender	1	$1,294.69
Right front door shell	1	$1,100.98
Body labor	45.1 hrs	$3,063.43
Paint and materials		$1,655.03
TOTAL		$8,846.21

Appraiser remarks

The left rear quarter panel and rear door show crumpling and a sheared bracket, which is mostly in line with the side impact described at the intersection. Some paint transfer and a cracked taillight lens fit the same sequence of contact. No earlier damage to the vehicle is known, and the inspection found no older repairs. The repair labor hours fit the extent of the deformation, and the parts list matches the areas struck. Two similar charges on the same day are being checked against the shop's invoices before approval. Repair can proceed once those checks clear.