Allen Auto Repair

71822 Arroyo Expressway
Katy, TX
Phone 346-555-3834

Repair Estimate

Estimate number:	EST-410617
Estimate date:	5-14-24
Customer:	Christine Yoder
Phone:	281-555-9852
Insurance claim:	C-1105
Vehicle:	2019 Ford F-150
VIN:	210F7P0D5D5J11336
License plate:	FCF-7023

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,272.39
Hood panel	1	$1,355.74
Left front fender	1	$878.80
Body labor	39.2 hrs	$2,667.73
Paint and materials		$1,294.62
TOTAL		$7,469.28

Appraiser remarks

The rear bumper cover is cracked across the left corner, the left quarter panel shows a dent with paint transfer near the wheel arch, and the tail lamp housing is broken. The damage pattern matches the impact as described, and no earlier damage to the vehicle is known from the file or the owner's account. Labor hours for removal, panel repair, refinishing and reassembly fit the extent of the damage shown in the photographs. Two similar charges posted on the same day are currently being verified with the shop before any payment is released. Repair plan: replace the bumper cover, straighten and refinish the quarter panel, and replace the tail lamp assembly, then recalibrate the parking sensors.