Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

Repair Estimate

Estimate number:	EST-958159
Estimate date:	06/11/2024
Customer:	Michele Williams
Phone:	832-555-7448
Insurance claim:	C-1106
Vehicle:	2021 Ford F-150
VIN:	DA8R12PD9E9NB2418
License plate:	52-MF02

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$375.67
Left tail lamp assembly	1	$210.30
Right tail lamp assembly	1	$243.91
Body labor	7.4 hrs	$503.29
Paint and materials		$365.13
TOTAL		$1,698.30

Appraiser remarks

The rear bumper cover, trunk lid and both taillight assemblies show crushing and paint transfer that match the rear-end impact described in the report. The damage pattern is largely consistent with the account given. Two similar charges recorded on the same day are being reviewed before the estimate is finalized. The labor hours listed are reasonable for the repairs needed, including panel replacement, refinishing and reinstalling the rear light units. No prior damage to the vehicle is known from the records available, and the repair plan will proceed once the review is complete.