King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-235772
Estimate date:	November 15, 2023
Customer:	Kimberly Gentry
Phone:	832-555-2150
Insurance claim:	C-1108
Vehicle:	2014 Honda Civic
VIN:	A5CG2UCR83P2B8019
License plate:	

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,612.03
Left front fender	1	$1,458.50
Left quarter panel	1	$987.42
Body labor	37.4 hrs	$2,542.07
Paint and materials		$1,231.89
TOTAL		$7,831.91

Appraiser remarks

The vehicle was struck on the front passenger side while the other driver was turning left across its path. The dmaage pattern is consistent with the impact described, with the bumper cover cracked, the fender crushed at the leading edge, and the headlamp assembly broken away from its mount. No earlier damage was found on the vehicle or on the panels examined. The proposed repair plan replaces the bumper cover and headlamp, straightens the fender, and refinishes the affected panels. The labor hours requested fit the extent of the damage shown. Two similar charges posted on the same day are being verified with the shop before payment is released.