Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-520505
Estimate date:	2024-12-21
Customer:	John Butler
Phone:	346-555-5923
Insurance claim:	C-1109
Vehicle:	2016 Nissan Altima
VIN:	RJJH9WFE9F5TW5652
License plate:	ZZE 735

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$333.76
Rear bumper cover	1	$275.59
Left tail lamp assembly	1	$265.54
Body labor	10.1 hrs	$687.58
Paint and materials		$347.99
TOTAL		$1,910.46

Appraiser remarks

The rear bumper cover is cracked across the center and the left tail lamp assembly is broken, with the trunk lid and rear panel showing crease lines consistent with the reported impact. Damage is confined to the rear section and the pattern lines up with a straight-on rear collision. The repair plan calls for replacing the bumper cover and tail lamp, repairing the trunk lid, and refinishing the affected panels. The labor hours requested fit the scope of this damage, and the invoiced line items show no repeated charges. We have no record or sign of earlier damage to this vehicle in the area being repaired. Recommend approval as submitted.