Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-875603
Estimate date:	13 Jun 2025
Customer:	Ethan Sharp
Phone:	346-555-4113
Insurance claim:	C-1110
Vehicle:	2016 Nissan Altima
VIN:	XBF4MWAG0Z69G5310
License plate:	862 HXP

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$824.28
Rear body panel	1	$841.21
Trunk lid	1	$563.28
Body labor	28.4 hrs	$1,930.86
Paint and materials		$940.31
TOTAL		$5,099.94

Appraiser remarks

The rear bumper cover is cracked across the center and the left quarter panel shows a crease with paint loss, which matches the rear-end impact described in the claim. The trnuk lid lock assembly and tail lamp housing also show deformation consistent with the force of the collision. Our plan is to replace the bumper cover, repair and refinish the quarter panel, and install a new tail lamp assembly. The labor hours requested fit the extent of the damage, and the parts list contains no duplicated line items. No prior damage to this vehicle is known from the records reviewed.