White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-911317
Estimate date:	December 16, 2024
Customer:	Samuel Murphy
Phone:	832-555-9381
Insurance claim:	C-1111
Vehicle:	2016 Jeep Cherokee
VIN:	UDYZAE2M1XDRV5779
License plate:	105 PJX

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$825.53
Headlamp assembly	1	$1,021.50
Left quarter panel	1	$708.63
Body labor	29.7 hrs	$2,018.55
Paint and materials		$1,246.19
TOTAL		$5,820.40

Appraiser remarks

The vehicle presents front-quarter damage on the driver side, consistent with a collision during a left-hand turn. The bumper cover is cracked and displaced, the headlamp assembly is broken, and the fender shows crush deformation with paint transfer along the seam. The crush pattern and the location of the contact points line up with the account given for how the impact occurred. Nothing on the car suggests older damage, and no prior repairs are recorded in its file. The proposed plan replaces the bumper cover, headlamp, and fender, followed by refinishing and a wheel alignment check. The labor hours listed are in line with the work described, and the invoices submitted show each charge once with no duplicates.