Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-862633
Estimate date:	19 May 2025
Customer:	Jason Hill
Phone:	346-555-3212
Insurance claim:	C-1113
Vehicle:	2011 Honda Civic
VIN:	K9UA2H4Z7FDGT5206
License plate:	873-QTP

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$346.06
Headlamp assembly	1	$199.60
Hood panel	1	$158.25
Body labor	9.2 hrs	$624.02
Paint and materials		$336.25
TOTAL		$1,664.18

Appraiser remarks

Right rear quarter panel and rear passenger door show crushed metal, a bent B-pillar trim line, and cracked tail lamp housing, all consistent with the side impact at the intersection as described. Paint transfer and deformation patterns line up with the reported point of contact, and no older collision repair or unrelated wear was observed on these panels. Proposed plan: replace rear door shell, repair quarter panel, install new tail lamp assembly, refinish affected areas, and perform a wheel alignment check. Labor hours are reasonable for this scope of work. Billing history on file shows no repeated charges for the same operations. Recommend approval as submitted.