Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-288809
Estimate date:	2023-11-01
Customer:	Jodi Sanchez
Phone:	281-555-5211
Insurance claim:	C-1114
Vehicle:	2016 Chevrolet Malibu
VIN:	
License plate:	ZZN0674

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,628.47
Rear bumper cover	1	$1,536.41
Trunk lid	1	$959.37
Body labor	35.9 hrs	$2,443.57
Paint and materials		$1,842.82
TOTAL		$8,410.64

Appraiser remarks

The rear bumper cover is cracked across its center and the left tail lamp assembly is shattered, with the trunk lid showing a crease that runs into the quarter panel. The pattern of crushed metal and displaced brackets lines up well with a straight-on rear impact, which is what the claimant described. Nothing I found suggests older collision damage, and the shop's records show no prior repairs in those areas. The plan calls for replacing the bumper cover and tail lamp, repairing and refinishing the trunk lid, and a pair of brackets, with labor hours that match the work involved. The invoice lines are single entries without repeated charges, and I recommend approving the estimate as written.