Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-483703
Estimate date:	July 3, 2025
Customer:	Joe Cohen
Phone:	713-555-4181
Insurance claim:	C-1115
Vehicle:	2024 Ford F-150
VIN:	F12G5PAK2PMGY2867
License plate:	89ZC779

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$991.42
Left tail lamp assembly	1	$1,000.99
Rear body panel	1	$596.95
Body labor	26.5 hrs	$1,799.44
Paint and materials		$1,068.73
TOTAL		$5,457.53

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp assembly broken and the trunk lid edge pushed inward. The damage pattern is consistent with the reported rear impact, and no earlier damage to this vehicle is known from the file or the owner's account. Repair plan calls for replacing the bumper cover and tail lamp, straightening the trunk lid flange, refinishing the affected panels, and checking the rear crush area for hidden deformation. The labor hours listed fit the scope of this damage. The invoices submitted show no repeated charges for the same operations, so the estimate is recommended for approval as written.