Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-362424
Estimate date:	17 Jan 2024
Customer:	Joshua Myers
Phone:	281-555-3258
Insurance claim:	C-1116
Vehicle:	2019 Ford F-150
VIN:	PSS5960U8RYKX9748
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,155.23
Headlamp assembly	1	$1,132.80
Left quarter panel	1	$945.57
Body labor	31.0 hrs	$2,108.73
Paint and materials		$941.12
TOTAL		$6,283.45

Appraiser remarks

The vehicle was inspected at the body shop following a sideswipe that occurred during a lane change. The damage to the right rear quarter panel, rear door, and bumper cover is consistent with the reported impact, with the contact ptatern running in the same direction the driver described. A few samll scratches on the lower rear door appear older than this loss and have been noetd separately so they are not included in the repair scope. The estimate lists panel replacement, refinishing, and bumper cover repair, and the labor hours shown are in line with the work needed to restore the damaegd areas. The shop's billing history for this vehicle shows no repeated cahrges for the same operations. The repair plan is approved as written, pending final supplement review after teardown.