Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-104976
Estimate date:	03/06/2025
Customer:	Benjamin Gonzalez
Phone:	346-555-6760
Insurance claim:	C-1121
Vehicle:	2019 Ford F-150
VIN:	N5763CNK1J5BL0942
License plate:	90-TT32

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,848.30
Rear bumper reinforcement	1	$1,245.04
Left tail lamp assembly	1	$1,065.77
Body labor	46.8 hrs	$3,180.02
Paint and materials		$1,264.52
TOTAL		$8,603.65

Appraiser remarks

The rear bumper cover is cracked and pushed inward on the driver side, with the trunk lid edge misaligned and the left tail lamp housing broken. The pattern of crush and scuffing lines up with the impact described in the claim, and nothing about it suggests a separate event. There is no sign of older damage or prior repair work on the panels or mounts. The plan is to replace the bumper cover, tail lamp assembly and reinforcement bar, realign the trunk lid, and refinish the affected areas. The labor hours listed are in line with this scope of work. The invoices we received show no duplicated or repeated charges.