Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-642169
Estimate date:	9-23-23
Customer:	Jessica Meyer
Phone:	832-555-3496
Insurance claim:	C-1122
Vehicle:	2022 Chevrolet Malibu
VIN:	SJTXGP7K2BNVK5375
License plate:	825 VZQ

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,785.91
Left quarter panel	1	$976.07
Left front fender	1	$1,225.68
Body labor	46.7 hrs	$3,177.89
Paint and materials		$1,653.81
TOTAL		$8,819.36

Appraiser remarks

Inspection of the front end shows a cracked bumper cover, a bent upper radiator support, and a broken headlamp assembly on the driver side, all in line with a frontal impact at low speed. The pattern of crush and paint transfer matches the collision as reported. Labor hours and parts listed on the estimate are consistent with this extent of damage, and the invoices contain no duplicated line items. Our records and the owner's account reveal no prior damage to this vehicle. Recommended repair: replace the bumper cover and headlamp, straihgten or replace the radiator support, refinish the affected panels, and recalibrate the forward sensor after reassembly.