Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-157630
Estimate date:	2023-10-22
Customer:	Kevin Mayer
Phone:	346-555-6064
Insurance claim:	C-1124
Vehicle:	2023 Ford F-150
VIN:	KH52TRYJ55UN45732
License plate:	KVI 238

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$602.87
Front bumper cover	1	$359.45
Left front fender	1	$480.54
Body labor	14.5 hrs	$985.94
Paint and materials		$517.41
TOTAL		$2,946.21

Appraiser remarks

Inspection of the rear bumper cover, left quarter panel, and tail lamp assembly shows damage consistent with the reported low-speed impact in the parking lot. Contact points line up with one another, and the pattern is what I would expect from the described event. A few faint scratches along the lower door edge appear older than this incident, possibly from prior wear, and have been noted separately from the new repair scope. The proposed plan covers replacing the bumper cover, repairing and refinishing the quarter panel, and replacing the lamp assembly. The labor hours requested fit the extent of the work. Billing reviewed so far shows no repeated charges for the same operation.