Allen Auto Repair

71822 Arroyo Expressway
Katy, TX
Phone 346-555-3834

Repair Estimate

Estimate number:	EST-697185
Estimate date:	5-12-24
Customer:	Sarah Walters
Phone:	346-555-6139
Insurance claim:	C-1125
Vehicle:	2014 Hyundai Elantra
VIN:	4XE9H5EJ8P3AY3032
License plate:	23M 838

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$581.84
Front bumper cover	1	$474.19
Left quarter panel	1	$461.75
Body labor	21.2 hrs	$1,438.29
Paint and materials		$773.63
TOTAL		$3,729.70

Appraiser remarks

Appraiser's remarks: The damage to the driver's side is consistent with the side impact described at the intersection, with crush to the front door, rocker panel and rear quarter panel. Repair labor hours are reasonable for the extent of the deformation and the parts listed. No prior damage to this vehicle is known from the file or the inspection. Two similar charges posted on the same day are currently under review and will be confirmed with the shop before payment. Recommended plan: replace the front door shell, straighten the rocker, refinish the affected panels and recalibrate the side curtain airbag sensor.