Osborne Auto Body

870 Samantha Crossing
League City, TX
Phone 281-555-7889

Repair Estimate

Estimate number:	EST-839996
Estimate date:	17 Jul 2023
Customer:	Paul Long
Phone:	832-555-7859
Insurance claim:	C-1126
Vehicle:	2019 Toyota Camry
VIN:	L89DWYA72GJGX0907
License plate:	HSD 171

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,843.30
Right front door shell	1	$1,242.07
Front bumper cover	1	$833.56
Body labor	63.0 hrs	$3,024.38
Paint and materials		$1,274.49
TOTAL		$8,217.80

Appraiser remarks

The rear bumper cover is cracked across its center with the left tail lamp housing broken, and the trunk lid shows a crease consistent with a low-speed strike from behind. The damage pattern lines up well with the impact as it was described, and no older damage to this vehicle is known to me. The shop's labor hours for this scope look a little high, so I would ask them to walk through the operations. Repair plan: replace the bumper cover, tail lamp assembly and trunk lid, then refinish and recheck alignment of the panel gaps.