Allen Auto Repair

71822 Arroyo Expressway
Katy, TX
Phone 346-555-3834

Repair Estimate

Estimate number:	EST-847124
Estimate date:	1-5-25
Customer:	Miranda Rodriguez
Phone:	346-555-1290
Insurance claim:	C-1128
Vehicle:	2016 Jeep Cherokee
VIN:	2Y8UGG7H3H3VP4000
License plate:	106 EHY

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$1,040.67
Rear bumper cover	1	$1,021.52
Trunk lid	1	$486.39
Body labor	25.7 hrs	$1,749.57
Paint and materials		$748.53
TOTAL		$5,046.68

Appraiser remarks

The vehicle presents rear bumper cover cracking, a deformed trunk lid edge, and a dented quarter panel that sits on the passenger side and at a lower height than the rear impact described in the claim, so the location and pattern of damage do not line up with that account. The repair plan calls for replaicng the rear bumper cover, straightening the trunk lid, refinishing the affected panels, and recalibrating the parking sensors. The labor hours listed fit the scope of this damage. The shop's invoices show no repeated charges for the same operations. No prior damage to this vehicle is known from our records or the inspection.