Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-934838
Estimate date:	December 6, 2024
Customer:	Jeffrey Davenport
Phone:	346-555-8222
Insurance claim:	C-1129
Vehicle:	2021 Kia Sorento
VIN:	YWN0X1V877VUD2797
License plate:	4272 AN

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$615.01
Rear body panel	1	$454.36
Rear bumper reinforcement	1	$422.72
Body labor	13.3 hrs	$906.51
Paint and materials		$439.97
TOTAL		$2,838.57

Appraiser remarks

The rear bumper cover is cracked and the trunk lid edge is bent, with the quarter panel showing a cresae that matches the reported rear-end impact. The damage pattern lines up well with how the collision was described. Repair labor hours are consistent with the extent of the work, and the parts and labor lines on the estimate show no duplicated charges. Nothing in the inspection or the vehicle's history points to earlier damgae in these areas. The plan is to replace the bumper cover, straighten the trunk lid, refinish the quarter panel and recheck alignment of the rear light assembly before final release.