Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-590178
Estimate date:	9 Feb 2024
Customer:	Kathleen Garcia
Phone:	713-555-0475
Insurance claim:	C-1130
Vehicle:	2015 Kia Sorento
VIN:	JNMP9T8L8NPY11070
License plate:	HTL 086

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$1,008.75
Right tail lamp assembly	1	$710.32
Trunk lid	1	$583.31
Body labor	25.5 hrs	$1,732.80
Paint and materials		$890.22
TOTAL		$4,925.40

Appraiser remarks

The rear bumper cover is cracked and pushed inward, the trunk lid edge is bent, and the left taillight housing is broken, all consistent with the reported rear-end impact. The damage pattern follows the force path described, and nothing in the vehicle suggests older collision work. The repair plan calls for replacing the bumper cover and taillight assembly, straightening the trunk lid edge, and refinishing the affected panels. The labor hours listed match the extent of the damage, and the parts and charges on the invoice appear once each with no repeated billing. The estimate is reasonable for the repairs needed.