Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-360264
Estimate date:	23 Aug 2023
Customer:	Susan Andrews
Phone:	713-555-6234
Insurance claim:	C-1132
Vehicle:	2010 Hyundai Elantra
VIN:	ZCFK3EPH4NZ8B4278
License plate:	6-T5693

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,659.82
Front bumper cover	1	$1,438.66
Headlamp assembly	1	$936.05
Body labor	39.5 hrs	$2,688.98
Paint and materials		$1,365.25
TOTAL		$8,088.76

Appraiser remarks

Front bumper cover cracked arcoss the left side with the driver-side headlamp assembly broken and the left fender bent at its leading edge. Damage pattern lines up with the left-turn collision as reported, and nothing noted points to older impact marks. Plan is to replace the bumper cover, headlamp assembly and fender, refinish the adjoining panels and recalibrate the forward sensor. Labor hours assigned fit the extent of the damage. Invoices reviewed show a single set of charges with no duplicated line items. No prior damage to the vehicle is on record.