Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-659777
Estimate date:	12-20-23
Customer:	Alexandra Harris
Phone:	832-555-9224
Insurance claim:	C-1133
Vehicle:	2015 Ford F-150
VIN:	9LDE99G98BWWG5777
License plate:	02-VK18

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,082.33
Front bumper cover	1	$945.86
Left quarter panel	1	$644.23
Body labor	28.0 hrs	$1,906.30
Paint and materials		$932.13
TOTAL		$5,510.85

Appraiser remarks

Vehicle inspected at the shop following a side impact at an intersection. Damage is concentrated on the driver-side rear quarter panel, with a crushed rear door, a cracked taillight housing, and scuffing along the rocker panel. The pattern is largely consistent with the reported collision direction. Repair plan calls for panel replacement, door realignment, and refinishing of the adjoining surfaces. The labor hours listed fit the scope of this damage, and the supplied inovices show no duplicated line items. No prior damage to this vehicle is on record. Estimate recommended for approval as submitted.