Guerrero Auto Body

83242 Brian Turnpike Suite 994
League City, TX
Phone 713-555-7464

Repair Estimate

Estimate number:	EST-967658
Estimate date:	2023-07-19
Customer:	Paula Castaneda
Phone:	832-555-5084
Insurance claim:	C-1134
Vehicle:	2021 Ford F-150
VIN:	40LKT6TX0V5UD9467
License plate:	13-9594X

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$899.77
Rear bumper cover	1	$1,101.83
Rear body panel	1	$1,024.17
Body labor	36.0 hrs	$2,451.29
Paint and materials		$1,279.67
TOTAL		$6,756.73

Appraiser remarks

Rear bumper cover cracked across the center with the lower valance torn free, and the left tail lamp assembly broken at its mounting points. The trunk lid shows a crease running into the panel edge, and the rear quarter panel has a shallow dent consistent with the reported rear-end impact. Structural rails appear straight and undamaged. The repair plan covers replacement of the bumper cover and valance, a new tail lamp, refinishing of the trunk lid, and paintless or conventional repair of the quarter panel as the metal allows. Labor hours are in line with the damage shown. No prior damage to this vehicle is known to us, and the invoices submitted show no repeated charges.