Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-470291
Estimate date:	2023-06-18
Customer:	Jon Ellis
Phone:	346-555-5847
Insurance claim:	C-1135
Vehicle:	2022 Jeep Cherokee
VIN:	L4D51KV695BZ24077
License plate:	9-90746C

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$1,394.83
Rear body panel	1	$1,298.51
Rear bumper cover	1	$712.10
Body labor	33.6 hrs	$2,282.20
Paint and materials		$1,406.66
TOTAL		$7,094.30

Appraiser remarks

The rear bumper cover is cracked across the center and the left tail lamp housing is broken, with scuffing on the trunk lid consistent with a rear-end impact. Some of the lower panel damage may not have come from this impact, and the exact cause of that wear is unclear from the photos. The billing history shows no repeated charges, and the labor hours given fit the extent of the visible damage. No earlier damage to this vehicle is known. The plan is to replace the bumper cover and tail lamp assembly, reapir and refinish the trunk lid, and recheck the lower panel once the bumper is off so any additional damage can be confirmed before work proceeds.