Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-293856
Estimate date:	2024-06-29
Customer:	Amber Jones
Phone:	832-555-0342
Insurance claim:	C-1136
Vehicle:	2024 Jeep Cherokee
VIN:	ZW4KZ76D2TPAX5373
License plate:	FYZ-9598

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$524.46
Left front fender	1	$360.79
Headlamp assembly	1	$488.12
Body labor	13.5 hrs	$918.24
Paint and materials		$466.66
TOTAL		$2,758.27

Appraiser remarks

Appraiser's remarks: The rear quarter panel, left taillight assembly and bumper cover show crushed and scraped areas that line up with the reported impact while the insured vehicle was turning left. Nothing observed suggests earlier damage to this vehicle, and the listed repair labor hours fit the extent of the work described. Two smiilar charges posted on the same day are currently under review and will be confirmed before payment. Repair plan: replace the bumper cover, quarter panel and taillight assembly, then refinish and recalibrate the sensors.